



Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



**FKA / FKB
3T - 3,5T**

**M8S
MT10
SVN**



VAS 6404

955750	16
955751	4
M 8-25	4
M 12-25	20
M 12-40	6
M 12-45	8
M 12-100	4
M 14-20	2
M 14-45	4
M 14-180	2
M 12x1,50-40	4
M 14x1,50-60	4
M 14x1,50-90	4
M 14x1,50-160	2
CHc TB 12-25	20
TFHc 12-45	8
M 12	22
M 14	2

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada


VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33A1



**M8S
MT10
SVN**

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 2

Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación




FIG. 3

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 5







FIG. 6





2106.300-RVA3-1 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



**FKA / FKB
3T - 3,5T**

M8S
MT10
SVN



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada


VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33A2



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 7




FIG. 8




FIG. 6




FIG. 9




FIG. 10






FIG. 11



**FKA / FKB
3T - 3,5T**

**M8S
MT10
SVN**



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300

284 Kg

07.09.2006

438-D-33A3



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 12




FIG. 13




FIG. 8





FIG. 6



2106.300-RVA3-2 00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



FKA / FKB
3T - 3,5T

M8S
MT10
SVN



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300

284 Kg

07.09.2006

438-D-33B1



M8S
MT10
SVN




FIG. 2

Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación




FIG. 3

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 14




FIG. 5





FIG. 6



2106.300-RVA3-2 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



**FKA / FKB
3T - 3,5T**

**M8S
MT10
SVN**



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada










VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33B2





2106.300-RVA3-3 00



**FKA / FKB
3T - 3,5T**

**M8S
MT10
SVN**








○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada

VAS 6403




2106.300


284 Kg | 07.09.2006 | 438-D-33B3




Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



**FKA / FKB
3,5T**




FKA 3,5T



VAS 6404

**M8S
MT10
SVN**




○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403



2106.300

284 Kg 07.09.2006 438-D-33C1



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 2

Réparation
Rebuilding
Ricostruzione
Instandsetzung
Reparación




FIG. 3

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 6




FIG. 5





FIG. 19


2106.300-RVA3-4 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



FKA / FKB
3,5T

M8S
MT10
SVN











○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300

284 Kg | 07.09.2006 | 438-D-33C2





2106.300-RVA3-4 | 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



FKA 3,5T

M8S
MT10
SVN



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300

284 Kg

07.09.2006

438-D-33C3



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 20




FIG. 22




FIG. 23




FIG. 16




FIG. 17






FIG. 21




2106.300-RVA3-5 00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero




FKA 4,6T / 5T



VAS 6404

M8S
MT10
SVN



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300

284 Kg

07.09.2006

438-D-33D1



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 2

Réparation
Rebuilding
Ricostruzione
Instandsetzung
Reparación




FIG. 3

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 5





FIG. 6

2106.300-RVA3-5 00



Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



FKA 4,6T / 5T



**M8S
MT10
SVN**



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33D2





FIG. 7




FIG. 8




FIG. 24




FIG. 6




FIG. 25




FIG. 17





FIG. 26




2106.300-RVA3-6 00



FKA 4,6T / 5T



**M8S
MT10
SVN**



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403

2106.300

284 Kg | 07.09.2006 | 438-D-33D3





FIG. 12




FIG. 13




FIG. 8







FIG. 6

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero




**FKA
4,6T / 5T**



VAS 6404

**M8S
MT10
SVN**



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada


VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33E1



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 2

Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación




FIG. 3

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 6




FIG. 5





FIG. 19



2106.300-RVA3-7 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



**FKA
4,6T / 5T**

M8S
MT10
SVN











○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300

284 Kg | 07.09.2006 | 438-D-33E2





2106.300-RVA3-7 | 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



**FKA
4,6T / 5T**

**M8S
MT10
SVN**



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada

VAS 6403



2106.300

284 Kg 07.09.2006 438-D-33E3





FIG. 20




FIG. 27




FIG. 6




FIG. 29




FIG. 30






FIG. 17





2106.300-RVA3-8 00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



FHS / FHL
3T / 3,5T

M8S
MT10
SVN



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300

284 Kg


07.09.2006

438-D-33F1




M8S
MT10
SVN

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41



Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación



Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 31




FIG. 5





FIG. 6


2106.300-RVA3-8 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



**FHS / FHL
3T / 3,5T**

M8S
MT10
SVN



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada


VAS 6403

2106.300










284 Kg

07.09.2006


438-D-33F2



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




2106.300-RVA3-9 00



**FHS / FHL
3T / 3,5T**

**M8S
MT10
SVN**



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada


VAS 6403

2106.300

284 Kg






07.09.2006

438-D-33F3




**M8S
MT10
SVN**

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41





2106.300-RVA3-9 00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



**FHS / FHL
3T / 3,5T**

**M8S
MT10
SVN**



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada


VAS 6403

2106.300

284 Kg


07.09.2006

438-D-33G1




1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41

**M8S
MT10
SVN**



Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación



Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 14




FIG. 6




FIG. 5




FIG. 15





FIG. 38



2106.300-RVA3-10 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



FHS / FHL
3T / 3,5T

M8S
MT10
SVN













○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403




2106.300


284 Kg 07.09.2006 438-D-33G2




2106.300-RVA3-10 00



**FHS / FHL
3T / 3,5T**



VAS 6404









VAS 6403




2106.300

284 Kg 07.09.2006 438-D-33G3




2106.300-RVA3-11 00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero




**FHS / FHL
3,5T**



VAS 6404

M8S
MT10
SVN



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33H1





FIG. 2

Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación




FIG. 3

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1

MZ 200




FIG. 4

MZ 260




FIG. 6

MZ 260




FIG. 5

MZ 200





FIG. 19

MZ 260



2106.300-RVA3-11 00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



FHS / FHL
3,5T

M8S
MT10
SVN



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403



2106.300

284 Kg 07.09.2006 438-D-33H2





FIG. 20




FIG. 6




FIG. 15




FIG. 35




FIG. 36




FIG. 17






FIG. 21




32

2106.300-RVA3-12 00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero




**FHS / FHL
4,6T - 5T**



VAS 6404

M8S
MT10
SVN



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada


VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33K1



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




FIG. 2




FIG. 3




FIG. 1




FIG. 4




FIG. 5





FIG. 6

2106.300 - RVA3-12 00



Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



**FHS / FHL
4,6T - 5T**



**M8S
MT10
SVN**



VAS 6404

○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403

2106.300

284 Kg

07.09.2006

438-D-33K2





FIG. 7




FIG. 8




FIG. 24




FIG. 6




FIG. 25






FIG. 37





32

2106.300-RVA3-13 00



**FHS / FHL
4,6T - 5T**



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada


VAS 6403

2106.300





284 Kg

07.09.2006


438-D-33K3




1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41




Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



**FHS / FHL
4,6T - 5T**



**M8S
MT10
SVN**



○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada


VAS 6403

2106.300

284 Kg


07.09.2006

438-D-33L1




**M8S
MT10
SVN**

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41



Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación



Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 1




FIG. 4




FIG. 6




FIG. 5





FIG. 19

2106.300-RVA3-14 00



Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



**FHS / FHL
4,6T - 5T**



**M8S
MT10
SVN**



VAS 6404








○ Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

VAS 6403
























2106.300

284 Kg 07.09.2006 438-D-33L2



2106.300-RVA3-14 00



VAS 6403

2106.300

284 Kg	07.09.2006	438-D-33M
2106.300-RVA3-15		00

	3,0 t	3,5 t	5,0 t & 4,6 t
FKA	R1 R2 	R1 R2 R3 R3L 	R2 R3 R3L LR-Volumen bei SuSi (4,6t) um jeweils 0,045m³ größer
	LH1 		
	LH2 		
FKB	LH1 		
	LH2 		
FHS			
FHL			

Radstand	Laderruhehöhe	Fzg.-Länge FKA/FKB (Überhang vorn 1004)	Fzg.-Länge FHS/FHL (Überhang vorn 1004)	Pritschenlänge (Innenmaß)	Fzg.GG	zul. VA-Last	zul. HA-Last
R 1 3250	LH 1 1650	A 1 5244 H: 990	L 1 5328 H: 1070	P 1 2120	3,0 t	1650 kg	1800 kg
R 2 3665	LH 2 1940	A 2 5909 H: 1240	L 2 6028 H: 1355	P 2 2700	3,5 t	1650 kg	2250 kg
R 3 4325	LH 3 2140	A 3 6944 H: 1615	L 3 6928 H: 1595	P 3 3400	4,6 t	1850 kg	3200 kg
		A 4 7344 H: 2015	L 4 6228 H: 1555	P 4 3600	5,0 t	1850 kg	3500 kg
			L 5 5558 H: 1300	P 5 4300			
			L 6 6138 H: 1465				
			L 7 6838 H: 1505				
			L 8 7038 H: 1705				


VAS 6403



2106.300

284 Kg 07.09.2006 438-D-33N

2106.300-RVA3-15 00



FKA / FKB
3T - 3,5T




FIG. 61



FKA 3,5T




FIG. 62



FKA
4,6T / 5T




FIG. 63



FKA
4,6T / 5T




FIG. 64



FHS / FHL
3T / 3,5T





FIG. 65



FHS / FHL
3T / 3,5T





FIG. 66



FHS / FHL
3T / 3,5T




FIG. 67



FHS / FHL
3,5T





FIG. 68



FHS / FHL
4,6T - 5T




FIG. 69



ATTENTION / CUIDADO

- Les roues de marbre doivent être remplacées **impérativement** par des roues référence : VAG 1920/04 "9175.9224"
- The bench wheels must **imperatively** be replaced by wheels reference : VAG 1920/04 "9175.9224"
- Die Richtbankräder sollen **unbedingt** durch Räder mit Referenznummer : VAG 1920/04 "9175.9224"
- Le ruote del banco devono **tassativamente** essere sostituite con ruote riferimento : VAG 1920/04 "9175.9224"
- Las ruedas del banco deben ser **imperativamente** reemplazadas por las ruedas referencias : VAG 1920/04 "9175.9224"

VAS 6403



2106.300

284 Kg 07.09.2006 438-D-33P
2106.300-RA3-16 00