





FA X TO C/S
ATTN: S. KUBOTA

2 pages



REP.	REFERENCE	PDS	NB
1	9107.743	221	1
2	9107.742	182	1
3	9107.703a	6,6	1
4	9107.703b	1,2	1
5	9107.704.1	2	4
6	9107.705	0,4	4
7	9107.710	0,3	1
8	9107.711	0,3	1
9	9107.712	0,5	1
10	9107.715	1	4
11	9107.716	0,2	8
12	9107.717.3	0,5	2
13	9107.718	0,4	1
14	9107.720	0,5	2
15	9107.721	0,4	2
16	9107.729	0,1	4
17	9107.730	0,02	8
18	9107.744	9	1
19	9107.745	2,5	1
20	9107.746	2,8	1
21	9107.747	1,2	1
22	9107.748	0,5	1
23	9107.749	2	1
24	9107.750	0,8	1
25	9107.754	4,2	1
26	9107.755	2,3	1
27	9107.756	2,3	1
28	HYP.2300.AS	6	1
29	VA10.501.A1	1	1
30	HYF.058.B	0,5	1
31	HYAC.019	0,1	1
32	MANET.E01	0,08	1
33	RESC.18016110	0,01	1
34	POIGNEE01	0,1	2
35	E40RCE1220	0,02	1

Circclips ø20	2
Anneau Truarc ø18	1
Anneau Truarc ø20	5
Anneau Truarc ø25	4
Goupille 6x30	2
Goupille 8x60	1

M 8-25	1
M 8-20	4
M 8-60	1
M 10-20	1
TC M 6-20	6
CHc 6-12	1

M 8	2
M 20	4

LLU10	1
MU 20	8


9107.033

PDS: 480 Kg 01.02.99 9107.033-1RA3



CELETTE®

VA10.501.A1



Repère / Part N° / Teil. Nr / Parte N° / Señal	Référence / Reference / Referenz. Nr / Riferimento / Referencia	Quantité / Quantity / Quantität / Quantità / Cantidad
1	VA10.50.A	1
2	VA10.50.B	1
3	VA10.50.C	1
4	V25.3	1
* 5	JOINT 9	1
* 6	JOINT 35	1
* 7	7830E.1400	1
Repair kit: <u>RN. 626</u>		

02.02.99

VA10.50A1-1RVA4