






SEVENNE / GRIFFON / RHONE x 1



A2 x 1
B2 x 1
C x 7
D x 1




TV400 x 2




MZ080 x 12
MZ140 x 4
MZ141 x 1
MZ142 x 1





MZ260 x 4
MZ601 x 2
MZ602 x 3




P100 x 8
P160 x 10
P220 x 6
P310 x 3





9212.013



REP	REFERENCE	NB		NB
1	7232.5001	1		
2	7232.5002	1		
4	7232.5004	1	M14-40	2
5	7232.5005	1	M14-180	2
6	7232.5006	2		
7	7232.5007	2		
17	7232.5017	1	M12x1,50-70	2
18	7232.5018	1		
19	7232.5019	2		
20	7232.5020	2		
21	7232.5021	1	M12x1,50-50	2
22	7232.5022	1		
23	7232.5023	2		
24	7232.5024	2		
27	7232.5027	1	M10-60	2
28	7232.5028	1	M10-110	2
29	7232.5029	2		
30	7232.5030	2		
31	7232.5031	1		
BXY1	BXY1	1		
32	7232.5032	1		
BXY1	BXY1	1		
34	7232.5034	2	M12x1,50-70	2
35	7232.5035	1	M12x1,50-100	2
36	7232.5036	2		
37	7232.5037	1	M12x1,50-40	2
38	7232.5038	1	M12x1,50-120	2
39	7232.5039	2		
40	7232.5040	2		
47	7232.5047	1	M12x1,50-110	2
48	7232.5048	1		
49	7232.5049	2		
50	7232.5050	2		
51	7232.5051	1	M12x1,50-110	2
52	7232.5052	1		
53	7232.5053	1		
54	7232.5054	2		
55	7232.5055	1	M10	2
56	7232.5056	1	M10	2
57	7232.5057	1	M6-20	2
58	7232.5058	1	M8	2
59	7232.5059	1	M8-50	2
60	7232.5060	1	M8	2
61	7232.5061	1	M8-30	2




3 / 5	7232.5A-L05-A3	01-07-22	00
-------	----------------	----------	----



SEVENNE / GRIFFON / RHONE x 1



A2 x 1
B2 x 1



TV400 x 2



MZ140 x 2



MZ200 x 2







P100 x 2

P220 x 2



9212.013

CONTROLE BERCEAU DEPOSE
KONTROLLE DES INTEGRALTRÄGER
CHECKING WITHOUT CRADLE IN PLACE
CONTROLLO SENZA TELAIO
CONTROL DEL BASTIDOR DESMONTADO



REP	REFERENCE	NB		NB
4	7232.5004	1	M14	2
5	7232.5005	1	M14-180	2
7	7232.5007	2		
21	7232.5021	1	M12	2
22	7232.5022	1	M12-80	2
62	7232.5062	2		

