



© Copyright 2009 CELETTE S.A. - All rights reserved. No part of this document may be reproduced in any form, by photostat, xerography or any other means, or incorporated into any informational retrieval system, electronic or mechanical, without the permission of the copyright owner.

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



A1 / A2

M8S
MT10
SVN




XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

7639.308

26 Kg	12.05.2009	420-D-29B1
7639.308-RVA3-1		00













MERCEDES BENZ





A1

**M8S
MT10
SVN**




XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada

MERCEDES BENZ

7639.308









26 Kg	24.08.2009	420-D-29C1
7639.308-RVA3-2		00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



A1 / A2

M8S
MT10
SVN



XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada




MERCEDES BENZ

7639.308


26 Kg	12.05.2009	420-D-29D1
7639.308-RVA3-2		00

Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



A3

M8S
MT10
SVN



XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada




MERCEDES BENZ

7639.308


26 Kg	12.05.2009	420-D-29E1
7639.308-RVA3-3		00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



A2

M8S
MT10
SVN



XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada


7639.308

26 Kg	24.08.2009	420-D-29F1
7639.308-RVA3-3		00

MERCEDES BENZ












Choc avant
Front crash
Frontreparatur
Urto anteriore
Choque delantero



M8S
MT10
SVN

A3




XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada

7639.308

26 Kg	12.05.2009	420-D-29G1
7639.308-RVA3-4		00















MERCEDES BENZ

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



M8S
MT10
SVN

A2




XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada



MERCEDES BENZ


7639.308		
26 Kg	24.08.2009	420-D-29H1
7639.308-RVA3-4		00

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



A3

**M8S
MT10
SVN**




XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecanica desmontada

7639.308

26 Kg	12.05.2009	420-D-29K1
7639.308-RVA3-5		00

MERCEDES BENZ

Choc arrière
Rear crash
Heckreparatur
Urto posteriore
Choque trasero



M8S
MT10
SVN

A3















FIG. 35



XX Avec ou sans mécanique
With or without mechanical elements
Con o senza parti meccaniche
Mit oder ohne Aggregate
Con ó sin mecánica desmontada

7639.308

26 Kg	12.05.2009	420-D-29L1
7639.308-RVA3-5		00

MERCEDES BENZ



Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación




FIG. 25

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 26

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 22

Contrôle
Checking
Controllo
Überprüfung
Control




FIG. 23

Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación




FIG. 24




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31

CONTROLE BERCEAU DEPOSE
KONTROLLE DES INTEGRALTRÄGER
CHECKING WITHOUT CRADLE IN PLACE
CONTROLLO SENZA TELAIO
CONTROL DEL BASTIDOR DESMONTADO




FIG. 32




FIG. 33

MERCEDES BENZ

7639.308

26 Kg	12.05.2009	420-D-29M1
7639.308-RA3-6		00

