

Inspection and Service on AXIS4000 and CMC4000

Inspection et Maintenance du système AXIS4000 et CMC4000



1. Inspection of the 3-arm-star for damages and planarity

Check on a surface plate with thickness gauge

Check with a straightedge

Inspecting against the light by putting both stars on each other

2. Inspection of the shaft

Check for:

- loose screws
- notches
- fretting
- worn parts
- missing parts

3. Inspection of cameras

Checking and calibration of the cameras

Check of the camera

Start diagnosis

Inclinometer calibration of the camera Calibration of cameras Certificate of calibration



1. Inspection du support 3 branches pour dommages et planéité

Vérification de la surface grâce à une jauge d'épaisseur
Vérification avec une règle à niveau
Vérification de la planéité du support par comparaison

2. Inspection de l'axe

Vérification de :

- serrage des vis
- encoches
- usure liée aux chocs
- pièces usagées
- pièces manquantes

3. Inspection des cameras

Vérification et calibration des caméras
Vérification de la caméra
Diagnostic
Calibration de la caméra
Certificat de calibration

