










SEVENNE / GRIFFON / RHONE x 1 	A2 x 1 B2 x 1 C x 5 D x 1 	TV400 x 4 	MZ080 x 1 MZ140 x 4 MZ141 x 1 MZ142 x 1 	MZ200 x 7 MZ260 x 8 MZ601 x 2 MZ602 x 2 	P100 x 6 P160 x 8 P220 x 8 P310 x 4 	9212.013 
--	--	--	--	--	--	---








SEVENNE / GRIFFON / RHONE x 1	A2 x 1 B2 x 1 C x 4 D x 1	TV400 x 4	MZ080 x 3 MZ140 x 4 MZ141 x 1 MZ142 x 1	MZ200 x 2 MZ260 x 6 MZ601 x 1 MZ602 x 1	P100 x 5 P160 x 8 P220 x 4 P310 x 2	9212.013
-------------------------------	------------------------------------	-----------	--	--	--	----------



REP	REFERENCE	NB		NB
1	7231.5001	1		
2	7231.5002	1		
B.12.120	B.12.120	4		
4	7231.5004	1	M14x1,50-220	2
5	7231.5005	1		
7	7231.5007	2		
8	7231.5008	1	M10	2
9	7231.5009	1	M10-130	2
14	7231.5014	1	M14x1,50-160	2
15	7231.5015	1		
17	7231.5017	2		
23	7231.5023	1		
BXY1	BXY1	1		
25	7231.5025	1	M12x1,50-170	2
26	7231.5026	1		
28	7231.5028	2		
31	7231.5031	1	M12x1,50-200	2
32	7231.5032	1		
34	7231.5034	2		
35	7231.5035	1	M10	4
36	7231.5036	1		
37	7231.5037	1	M8	2
38	7231.5038	1	M8-40	2
39	7231.5039	1	M14	2
40	7231.5040	1	M14-30	2





SEVENNE / GRIFFON / RHONE x 1




A2 x 1

B2 x 1

C x 3

D x 1



MZ080 x 5

MZ140 x 4


MZ141 x 1

MZ142 x 1






P100 x 9

P160 x 2




DIAG.

REP	REFERENCE	NB			NB
4	7231.5004	1			2
5	7231.5005	1			
6	7231.5006	2			
14	7231.5014	1			2
15	7231.5015	1			
16	7231.5016	2			
18	7231.5018	1			2
19	7231.5019	1			
20	7231.5020	2			
23	7231.5023	1			
BXY1	BXY1	1			
25	7231.5025	1			2
26	7231.5026	1			
27	7231.5027	2			
31	7231.5031	1			2
32	7231.5032	1			
33	7231.5033	2			




DIAG.



SEVENNE / GRIFFON / RHONE x 1




A2 x 1
B2 x 1




MZ141 x 1
MZ142 x 1



MZ200 x 2



P100 x 4



CONTROLE BERCEAU DEPOSE
KONTROLLE DES INTEGRALTRÄGER
CHECKING WITHOUT CRADLE IN PLACE
CONTROLLO SENZA TELAIO
CONTROL DEL BASTIDOR DESMONTADO

REP	REFERENCE	NB				NB
4	7231.5004	1	M14			2
5	7231.5005	1	M14-120			2
14	7231.5014	1	M14			2
15	7231.5015	1	M14-130			2
41	7231.5041	2				

