




Mod. 88 →

N° Chassis : 331066 (4 Portes - 4 Door)
N° Chassis : 806451 (5 Portes - 5 Door)


REP.	REFERENCE	PDS	NB	MZ
28	520.728	3,8	1	602
29	520.729	3,8	1	601
30	520.730	0,7	2	

complément au
complementary set to
complemento al
zusatz zu



520.300

520.309

9 Kg	20.10.93	439-D-6B
------	----------	----------



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36



Réparation
Rebuilding
Riconstruzione
Instandsetzung
Reparación

Contrôle
Checking
Controllo
Überprüfung
Control