



SEVENNE / GRIFFON / RHONE x 1




A x 1
B x 1
C x 4
D x 1



TV400 x 4




MZ080 x 6
MZ140 x 4
MZ141 x 1
MZ142 x 1



MZ200 x 2
MZ260 x 9
MZ601 x 4
MZ602 x 3

P100 x 11
P160 x 10
P220 x 4
P310 x 5



9123.013 / 9123.023





FIG.2
CONTROLE
CHECKING
CONTROLLO
ÜBERPRÜGUNG
CONTROL



REPARATION
REBUILDING
RICONSTRUZIONE
INSTANSETZUNG
REPARACION






FIG:3

FIG:7



REP	REFERENCE	NB		NB
1	2683.5001	1	M8-30	4
2	2683.5002	1		
3	2683.5003	1		
4	2683.5004	1		
5	2683.5005	1	M6-35	2
6	2683.5006	1		
37	2683.5037	1	M6-35	2
38	2683.5038	1		
7	2683.5007	1	M10-30	2
8	2683.5008	1	M10-30	2
9	2683.5009	1	M10	6
10	2683.5010	1	M10-30	6
11	2683.5011	2	M12-30	2
12	2683.5012	1	M8-30	2
36	2683.5036	1		
FT40	FRT.D40.01	1		
13	2683.5013	1	M10-40	2
14	2683.5014	1		
16	2683.5016	1	M12x1,50-90	2
17	2683.5017	1		
18	2683.5018	2		
19	2683.5019	1		
20	2683.5020	1		
21	2683.5021	1		
22	2683.5022	1		
23	2683.5023	1		
24	2683.5024	1		
25	2683.5025	1	M10-70	4
26	2683.5026	1		
27	2683.5027	2		
28	2683.5028	1	M10-30	4
29	2683.5029	1		
30	2683.5030	1		
31	2683.5031	1		
32	2683.5032	1		
33	2683.5033	1		
34	2683.5034	1	M8-40	2
35	2683.5035	1	M8-40	2







FIG.1





SEVENNE / GRIFFON / RHONE x 1




A x 1

B x 1

C x 3

D x 1



TV400 x 4



MZ080 x 10

MZ140 x 2



MZ200 x 2

MZ260 x 2



P100 x 10

P160 x 2

P220 x 4



9123.013 / 9123.023



REP	REFERENCE	NB		NB
3	2683.5003	1		
4	2683.5004	1		
13	2683.5013	1	M10-40	2
14	2683.5014	1		
15	2683.5015	2		
16	2683.5016	1	M12x1,50-140	2
17	2683.5017	1		
19	2683.5019	1		
20	2683.5020	1		
21	2683.5021	1		
22	2683.5022	1		
23	2683.5023	1		
24	2683.5024	1		
25	2683.5025	1	M10-70	4
26	2683.5026	1		
32	2683.5032	1		
33	2683.5033	1		

